

FIG. 1




FIG. 2





FIG. 3



ॐ




FIG. 5




FIG. 6

FIG. 7 is a schematic diagram of the excitation circuit of the motor of FIG. 1. The circuit includes a line input, a switch, a fuse, a +24V source, a ground, an excitation circuit, and a motor winding.




FIG. 7





FIG. 8




FIG. 9






FIG. 10




FIG. 11

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17






FIG. 20




FIG. 21




FIG. 22